

17977

IED Report

REL TO

CLASSIFICATION: SECRET RELEASABILITY: USA,

ACGU

IED- 2011-

TRACKING NUMBER: 20111122093938SMB54382 DATE DISCOVERED: Nov-22

09:39

CALL SIGN: Jester REPORTING UNIT: 752

PRIMARY SAFE 38SMB5440917894 SECONDARY SAFE Report

AREA(MGRS): AREA(MGRS):

MGRS: 38SMB5438217977 EVENT TYPE: Explosi

COALITION:

KIA: WIA: KIA: WIA: KIA: WIA:

O O O O O O O

Equipment Used 1

EQUIPMENT USED TYPE: Vehicle EQUIPMENT USED NAME: JERRV

Equipment Used 2

EQUIPMENT USED TYPE: PPE EQUIPMENT USED NAME: Other

Equipment Used 3

Equipment Used

EQUIPMENT USED TYPE: Crew EQUIPMENT USED NAME: Other

Team Data

23-November-11 Page 1of 4



SERVICE AFFILIATION: USA

EOD NOTIFICATION: 2011-Nov-22 09:40

EOD FOB DEPARTURE: 2011-Nov-22 09:55 EOD SCENE ARRIVAL: 2011-Nov-22 10:13

EOD SCENE

EOD MISSION 2011-Nov-22 11:25 2011-Nov-22 11:40 **DEPARTURE:**

COMPLETE:

Site Data

SITE MARKED: No

MARKING DETAILS: Not Reported

CIVILIAN ACTIVITY: No Civilians Present - Area Usually Vacated

REFERENCE POINT: No

AIMING POINT DETAILS: Not Reported

FIRING POINT DETAILS: Not Reported

FIRING POINT MGRS: Not Reported

LIGHT CONDITIONS: Daytime

WEATHER: Clear

ROUTE PATROL: Unknown

LAST TIME ROUTE

CLEARED:

Not Reported

ANALYSIS: Not Reported

Devices

Device 1

DEVICE DESCRIPTION: Not Reported

MGRS: 38SMB5437917940

PLACEMENT: LOCATION: Road - Right Surface

Side

CONTAINER: Unknown CONTAINER SUB-TYPE: Not Reported

23-November-11 Page 2of 4

USCENTCOM FOIA 17-0112 152 08/08/2018



HOW DEVICE WAS FOUND: Detonation WHO FOUND DEVICE: Not Applicable

ACTION TAKEN: Post Blast

EXPLOSIVE EFFECT: Fragmentation

Blast

MAIN CHARGE CONFIGURATION: Directional-EFP

CASUALTIES: No SUICIDE DEVICE: No FIRST RESPONDER TARGETED: No

POST BLAST: Yes PARTIAL BUILD: No

Targets

TARGET PRECEDENCE: Primary AFFILIATION: Coalition

COUNTRY: USA - UNITED TARGET TYPE: Military

STATES

DETAILS: Convoy INTENDED EFFECT: Anti-Armor

DESCRIPTION: Not Reported

Initiators

TYPE: Unknown INITIATION SUB-TYPE: Not

Reported

INITIATION DETAIL: Not Unknown

Reported

ARMING: Not DTMF: No

Rep_i rted

MAKE: Not MODEL: Not

Reported Reported

RECEIVER REMOTED: Unknown RECEIVER REMOTED DISTANCE(M): 0

Munitions

CATEGORY: UBE MUNITIONS TYPE: Unknown

NAME: Not Reported QUANTITY: Not Reported

COUNTRY: UC - UNKNOWN

COUNTRY

WEIGHT: SIZE: Not Reported Not

Reported

23-November-11 Page 3 of 4

USCENTCOM FOIA 17-0112 153 08/08/2018

NET EXPLOSIVE WEIGHT: 30 lb

LOT NUMBER: Not Reported SERIAL NUMBER: Not Reported

DETAILS: Not Reported

Fusing

DETAILS: Not Reported COUNTRY: UC - Unknown Country

Render Safe

RSP: Not Attempted RENDER SAFE DETAILS: Not Reported

23-November-11 Page 4of 4

USCENTCOM FOIA 17-0112 154 08/08/2018



****SIGACT CLOSED****

SIGACT Report

TITLE: (EXPLOSIVE HAZARD) IED EXPLOSION RPT (Directional IED) 2-5 CAV,

1-1 AAB IVO (ROUTE MSR TAMPA): 0 INJ/DAM

TRACKING NUMBER: 20111122093938SMB5438217977

REPORT PRECEDENCE: Flash

CLASSIFICATION: SECRET RELEASABILITY: REL TO USA, FVEY

REPORTING UNIT NAME: USD-C G3 SIGACT

MANAGER

REPORT SOURCE:

Coalition

SPOT Section

UNIT NAME INVOLVED: 2-5 CAV, 1-1 AAB CALL SIGN: Not Reported

TYPE OF INVOLVED UNIT: CF INVOLVED UNIT ACTIVITY: Other

INCIDENT REPORTED BY: Coalition Forces BATTLESPACE LEAD: Coalition

TIP REPORTED BY: Not Reported DTG CREATED (LOCAL): 2011-11-22

11:47:17

DTG OF INCIDENT (LOCAL): 2011-11-22 DTG UPDATED (LOCAL): 2011-11-23

09:39:00 16:39:37

Location

MGRS: 38SMB5437917940 ROUTE: MSR TAMPA

Events

EVENT TYPE: Explosive Hazard MODES OF ATTACK: Directional IED

EVENT CATEGORY: IED Explosion

23-November-11 Page 1of 6
SECRET//REL TO USA, FVEY

USCENTCOM FOIA 17-0112 155 08/08/2018

PRIMARY INTENDED OUTCOME: Anti-Armor

SUICIDE?: No EFFECTIVE HIT?: No

COORDINATED ATTACK: No

COMPLEX ATTACK: No

COUNTER ATTACK: No

MEDEVAC REQUESTED: No

BLOWN IN PLACE: No

SUMMARY: USF REPORT

SUMMARY: AT 22 0939 NOV 11, AN IED DETONATED ON THE LEAD CAIMAN OF A 3/B/2-5 CAV CIED PATROL TRAVELING SOUTH ON MSR TAMPA IN BABIL. THE PATROL REPORTED NO CASUALTIES AND 1 X CAIMAN DAMAGED THAT REQUIRED RECOVERY. MSR TAMPA WAS TURNED BLACK. PREDATOR MOVED TO THE SITE TO PROVIDE OVERWATCH. IP ONSITE PROVIDED ADDITIONAL SECURITY. 2-5 CAV REPORTED THAT IMMEDIATELY AFTER THE BLAST, 4 X LN FLED SITE TO A HOUSE IN THE AREA. SHADOW PROVIDED OVERWATCH OF THE HOUSE. AN ADDITIONAL QRF ELEMENT AND ISF RESPONDED TO THE HOUSE, CORDONED THE AREA, AND CONDUCTED A COMBINED SEARCH WITH NSTR. EOD CONDUCTED PBA AT THE BLAST SITE AND ASSESSED THAT THE BLAST WAS THE RESULT OF AN EFP. THE SITE WAS CLEARED AND MSR TAMPA WAS CHANGED FROM BLACK TO AMBER. 3/B/2-5 CAV, QRF, EOD, AND REVOVERY RTB COS KALSU AT 1147.

1/1 AAB S2 ASSESSMENT: BASED ON THE LOCATION AND THE TYPE OF MUNITION USED, THIS ATTACK WAS LIKELY CONDUCTED BY

(b)((1)1.4c, (b)(6)	
(b)(1)1.	4c	OF
INITIATION SYSTEM AND NO C	OMMAND WIRE	E FOUND ON SCENE IS
CONSISTENT WITH	(b)(1)1.4c, ((b)(6)
(b)(1)1	.4c	
(b)(1)1.4c , BETWEEN CHEC	CKPOINTS 9A AN	ND 12A ON MSR TAMPA
(b)(1)1.4c , IT IS LIKELY TI	HAT USF C-IED P	RESENCE IN THE AREA
HAS CAUSED HIM TO CHANGE	LOCATIONS.	
USD-C G2 ASSESSMENT:	(b)(1))1.4c
(b)(1	1)1.4c	
(b)(1)1.4c		PATROL WHILE

23-November-11 Page 2of 6
SECRET//REL TO USA, FVEY



(b)(1)1.4c				
RESULTED IN ONE MRAP DAMAGED BUT NO CASUALTIES.				
APPROXIMATELY 400M TO THE NORTH OF	(b)(1)1.4c	AND		
DAMAGED BUT NO CASUALTIES. TODAY'S ATTAC	CK OCCURRI	ED		
TRAVELING NORTH ON TAMPA RESULTING IN O	NE CAIMAN			

USF CONVOYS TRAVELING ON MSR TAMPA USING IEDS. HOWEVER, THERE IS NO INFORMATION OR REPORTING AT THIS TIME TO INDICATE INDIVIDUAL(S) OR GROUP RESPONSIBLE FOR THIS ATTACK.

EOD ASSESSMENT: 752/2/2 RESPONDED TO A PBA AT 38S MB 54379 17940 ISO 1/1 CAV. TEAM ARRIVED ON SCENE AND THE BARBARIAN BLUE COMMANDER REPORTED THAT WHILE TRAVELING SOUTH ON MSR TAMPA, THERE WAS A DETONATION NEXT TO THE LEAD VEHICLE ON THE WEST SIDE OF THE ROAD. VEHICLE PUSHED THROUGH THE BLAST AREA AND STOPPED APPROXIMATELY 100M FROM THE BLAST SEAT. TEAM PERFORMED A RECON AND EXPLOITED THE SITE. TEAM DISCOVERED THAT THE BLAS' DAMAGE ON THE THE BLAST SEAT WAS 20' VEHICLE WAS (b)(1)1.4g FROM THE ROAD AND MEASURED 40" X 32" X 8" DEEP. THE BLAST SEAT WAS CONSISTENT WITH APPROXIMATELY 30 POUNDS OF UNKNOWN BULK EXPLOSIVES. TEAM DISCOVERED NO FURTHER EVIDENCE TO SUGJEST DEVICE INITIATION AND FOUND NO FURTHER EXPLOSIVE HAZARDS.

BDA:

1 X CAIMAN DAMAGED

CLOSED

ENEMY:			COALITION:		
KIA:	WIA:	DET:	KIA:	WIA:	ABD:
0	0	0	0	0	0

CIVILIAN:			HOST NATION:		
KIA:	WIA:	ABD:	KIA:	WIA:	ABD:
0	0	0	0	0	0

CCIR Status

23-November-11 Page 3 of 6

USCENTCOM FOIA 17-0112



SUMMARY: USF-I DCG(O) IR 17: Any attack utilizing RKG-3, EFP, SVBIED and/or

PBIED

GROUP: USD-C G3 SIGACT MANAGER

Capture Details

Casualty Details

Target(s) of Attack

PRECEDENCE: Primary TYPE: Coalition

AFFILIATION: Coalition SECT: Unknown

DETAILS: Convoy NATIONALITY: IRAQ

STATUS: Damaged

DESCRIPTION: Not Reported

Indirect Fire Information

Vehicle/Convoy Details

NUMBER OF VEHICLES: 0

DISTANCE BETWEEN VEHICLES: 0 Meters

CONVOY SPEED: 0 MPH

158 08/08/2018

NEAREST ECM DIST TO IED: 0 Meters

NEAREST ECM DIST TO VEHICLE STRUCK: 0 Meters

OTHER COUNTERMEASURES ON VEHICLE STRUCK: Not Reported

23-November-11 Page 4of 6

USCENTCOM FOIA 17-0112



VEHICLE SUMMARY:	Not Reported

DRUGREP Details
FACILITY TYPE: Not Reported
Drugs Found
- CO
Chemicals Found
201
Equipment Found
9,10

Reintegration Details					
REINTEGRATION OPEN:			No		
REINTEGRATION OPEN COMMEN	TS:		No		
NUMBER OF REINTEGRATEES:			0		
	FOLLOW UP DATES	COMPLETED	COMPLETED DATE		
VETTING DATE:	Not Reported	No	Not Reported		
COMMUNITY TALK DATE:	Not Reported	No	Not Reported		
REINTEGRATION DATE:	Not Reported	No	Not Reported		

23-November-11 Page 5of 6

USCENTCOM FOIA 17-0112 159 08/08/2018



7 DAY FOLLOW UP: **Not Reported** No **Not Reported Not Reported** 30 DAY FOLLOW UP: **Not Reported** No **60 DAY FOLLOW UP: Not Reported** No **Not Reported** 90 DAY FOLLOW UP: **Not Reported Not Reported** No 180 DAY FOLLOW UP: Not Reported No Not Reported

REINTEGRATION CLOSED: No REINTEGRATION CLOSED REASON: Not

Reported

REINTEGRATION CLOSED COMMENTS:

USCENTCOM FOIA 17-0112 160 08/08/2018



(752 | 2 | 2)

220940CNOV11

1/1 CAV SUPPORTED BCT

(b)(3), (b)(6)

<u>2/5/1/1</u>

TEAM LEADER

ON SCENE COMM

38SMB5437917940 MGRS GRID LOCATION MSR TAMPA MSR

Sout DIRECTION OF

IED

TYPE OF REPORT

Explosion
EVENT CATEGORY

Othe METHOD OF EM

SIGACT #: 20111122093 .38SMr 5438217977

CIDNE #: IED-20111122077938SMB5438217977

CCIR: USD-C15,18 DCG-O

	CF	LN	IA/IP/NP	<u>E</u>	U.S. Civilian	Coalition
KIA	0	0	0	0	0	
WIA	O ISCENITCOM	O FOIA 17-0112	0	0	0	161 0







USCENTCOM FOIA 17-0112 162 0



Aerial / Map View of Site





EOD Notification:

EOD FOB Departure:

EOD Scene Arrival:

EOD Scene Departure:

EOD Mission Complete:




USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

163 0



Scene Diagram



USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

164 0



Narrative / Background

(SECRET // REL TO USA, FVEY) 752/2/2 responded to a PBA at 38S MB 54379 17940 ISO 1/1 CAV. arrived on scene and the Barbarian Blue Commander reported that while traveling south on MSR there was a detonation next to the lead vehicle on the west side of the road. Vehicle pushed throublast area and stopped approximately 100m from the blast seat. Team performed a recon and exp the site. Team discovered that the blast damage to the vehicle was consistent with a blast seat was 20' from the road and measured 40" x 32" x 8" deep. The blast seat was consistent approximately 30 pounds of unknown bulk explosives. Team discovered no further evidence to sidevice initiation and found no further explosive hazards. MC: 221140CNOV11.

USCENTCOM FOIA 17-0112 165 0



Evidence List

	Evidence List				
Item/Bag #	Quantity		Evidence		
1		(b)(1)1.4c	Release		
		6-			
		N6610Aeg			

166 0 USCENTCOM FOIA 17-0112



Photographs of Scene



Aerial View

USCENTCOM FOIA 17-0112 167 0



Photographs of Scene



Return to

USCENTCOM FOIA 17-0112

SECRET // REL TO USA, ACGU

100



Photographs of Scene



North

USCENTCOM FOIA 17-0112 169 0



Photographs of Scene



East

USCENTCOM FOIA 17-0112 170 0



Photographs of Scene



South

USCENTCOM FOIA 17-0112 171 0



Photographs of Scene



West

USCENTCOM FOIA 17-0112 172 0



Photographs of Scene




Blast seat

USCENTCOM FOIA 17-0112 173 0



Photographs of Scene



Blast damage

USCENTCOM FOIA 17-0112 174 0



Photographs of Scene



(b)(1)1.4c

found on tire rim

USCENTCOM FOIA 17-0112 175 0



Photographs of Scene



Blast damage

USCENTCOM FOIA 17-0112 176 0



Photographs of Scene



EFP entry point on hood

USCENTCOM FOIA 17-0112



Photographs of Scene



EFP Direction of travel

USCENTCOM FOIA 17-0112 178 0



Photographs of Scene



Damage on driver side from fragments traveling in engine compartment

USCENTCOM FOIA 17-0112 179 0



Photographs of Scene



Damage to (b)(1)1.4g

USCENTCOM FOIA 17-0112

-SECRET // REL TO USA, ACGU

180 0



Photographs of Scene



Damage to (b)(1)1.4g

USCENTCOM FOIA 17-0112 181 0



Photographs of Scene



Damage to (b)(1)1.4g

USCENTCOM FOIA 17-0112 182 0



Photographs of Scene



Damage to (b)(1)1.49

USCENTCOM FOIA 17-0112 183 0



Photographs of Scene



Piece of copper recovered from (b)(1)1.4g

USCENTCOM FOIA 17-0112



Photographs of Scene



Vehicle damage

USCENTCOM FOIA 17-0112 185 0



Photographs of Scene



Damage to light

USCENTCOM FOIA 17-0112 186 0



Photographs of Scene



Vehicle damage

USCENTCOM FOIA 17-0112 187 0



Photographs of Scene



Damage to TC window

USCENTCOM FOIA 17-0112 188 0



Photographs of Scene



DVE cable servered

USCENTCOM FOIA 17-0112 189 0



Photographs of Scene



(b)(1)1.4c

on gunners ammo can

USCENTCOM FOIA 17-0112 190 0



Photographs of Scene



Impact on gunners chicken shield

USCENTCOM FOIA 17-0112 191 0



Photographs of Scene



(b)(1)1.4c

recovered from vehicle

USCENTCOM FOIA 17-0112 192 0